



T&T Pump Co., Inc.

SERVICE BULLETIN

BULLETIN #TTSB11/51302

REFERENCE: H Series Plumbing

During recent service calls to various customer installations our service technicians have seen systems where the plumbing did not align properly with the pumps inlet and discharge connections. In some cases the plumbing was forced into position putting excessive load on the pump and the pumps mounting feet. In some instances this excessive loading has lead to broken front feet and casing bolt failure. In order to insure warranties, proper installation must be performed. Please review the diagram below.

